

4900 N. Tumbleweed Road, Bldg 1.  
P O Box 86  
ELOY AZ 85231, USA



Telephone: 520-466-2655  
Fax: 520-466-2656  
[www.rigginginnovations.com](http://www.rigginginnovations.com)

November 5, 2008

### AVIATOR REPACK CYCLES

Rigging Innovations authorizes a 1 year repack cycle for the Aviator parachute system. However, this interval does not supersede the repack cycle mandated either by the national aviation authority of the country of use or any relevant military organization of that country.

For repack cycles longer than six months, the Aviator should have an interim external visual inspection every six months. If there are signs of damage or contamination, the Aviator should then be inspected and repaired as needed, before being repacked and returned to service.

Sincerely,

**RIGGING INNOVATIONS INC**

A handwritten signature in black ink, appearing to read 'Sandy R. Reid', written in a cursive style.

**SANDY R. REID**  
PRESIDENT