



SERVICE BULLETIN

DATE:	DEC 1, 1990	SERVICE BULLETIN #	1509	# OF PAGES:	2
SUBJECT:	RSL LANYARD LENGTH- TALON/TELESIS/CLASSIC				
STATUS:	ADVISORY				

IDENTIFICATION: All Talon/Classic containers P/N 4111-(). All Telesis containers P/N 4113-(). RSL lanyards P/N 2811-(1) & 2811-(2).

BACKGROUND: In order to ensure the installation of the correct RSL lanyards on the above container systems, the attached table will allow identification of the proper RSL configurations.

SERVICE BULLETIN: If the RSL lanyard does not fit properly, check the length against the chart for proper mating/compatibility.

COMPLIANCE DATE: AT EACH REPACK.

AUTHORITY:

SANDY R. REID, PRESIDENT
Rigging Innovations Inc.
P O Box 86, Eloy AZ 85231, USA
Telephone: 520-466-2655
FAX: 520-4662656

DISTRIBUTION:

1. All Rigging Innovations Dealers.
2. All Parachuting Publications.
3. National Aero Clubs, Parachuting Section.
4. Military Parachute Organizations.