



SERVICE BULLETIN

DATE: Dec 1, 2000 **SERVICE BULLETIN #** SB-1539 **# OF PAGES:** 1
SUBJECT: RSL SLEEVE
STATUS: RECOMMENDED

IDENTIFICATION: Talon 2, Telesis 2

BACKGROUND:

An incident occurred with a Telesis 2 system where there was a main/reserve entanglement. During the investigation, one of the scenarios focused on the RSL and the possibility of its being snagged and activating the reserve before releasing the main canopy. While there was no direct proof of the RSL causing the entanglement, further testing resulted in the development of a protective sleeve to preclude accidental snagging of the RSL.

The Talon 2 and Telesis 2 utilize the same RSL configuration. Talon 2 owners who have an RSL installed may wish to have their system modified as well.

SERVICE BULLETIN:

1. Install the RSL sleeve in accordance with PMP-1254.

COMPLIANCE DATE: None

AUTHORITY:

SANDY R. REID, PRESIDENT
Rigging Innovations Inc.
P O Box 86, Eloy AZ 85231
Telephone: 520.466.2655
FAX: 520.466.2656

DISTRIBUTION:

1. All registered owners affected by the Service Bulletin.
2. All Rigging Innovations Dealers.
3. Parachute Industry Association
4. All Parachuting Publications.
5. National Aero Clubs, Parachuting Section.
6. Military Parachute Organizations.