



Deutscher Fallschirmsportverband (DFV) e.V.
Deutscher Aero-Club (DAeC) e.V. Luftsportgerätebüro
Verband unabhängiger Prüfer von Luftsportgerät e.V.

An alle Vereine/Schulen/ Fallschirmtechniker/ Fallschirmwarte

SICHERHEITSMITTEILUNG für Gurtzeuge

herausgegeben: 2016-01-06

Nummer: 01/2016

Bezug: PRODUCT SERVICE BULLETIN 2016-01 von Parachute Systems

Betroffene Muster: alle Vortex Gurtzeuge mit einem Mini-3-Ringsystem aus Edelstahl bei dem das Logo „DSF“ auf dem Base-Ring (Schlitzring) des 3-Ringsystems eingepreßt ist.

Status: **Die betroffenen Gurtzeuge mit diesen Ringen sind bis auf Widerruf gegroundet!!!**



Grund: Bruch eines Ringes

Maßnahmen: Es sind alle Gurtzeuge vom Typ Vortex zu kontrollieren, ob am 3-Ringsystem Edelstahl-Schlitzringe der Firma DSF eingebaut sind.

Durchzuführen bis: **vor dem nächsten Sprung!**

Bemerkungen: Das Logo befindet sich auf dem Schlitzring (Ring der am Gurtzeug befestigt ist).
Die Firma Parachute Systems bemüht sich um eine schnelle Klärung des Problems.
In der Anlage findet Ihr die Mitteilung der Firma VSE.

Verteiler: Techniker, Warte, Händler, Vereine, Sprungzentren.

Dresden , den 2016-01-05

Referat Technik DFV

Ralf Homuth - Geschäftsstellenleiter VuPL



32 Melbourne Road, Dalbridge
Durban S A 4014
Tel: (031) 304 8035 / Fax: (031) 304 8082
email: admin@parachutesystems.co.za

Reg No: 2002/50029/23

PRODUCT SERVICE BULLETIN 2016-01 (PSB # 2016-01)

ISSUE DATE: 4th January 2016

SUBJECT: Stainless Steel Mini Base Ring

STATUS: Ground Equipment Until Further Notice

IDENTIFICATION: PSB # 2016-01

Affected Vortex Rigs: To be updated ASAP.

Subject to a notification on Saturday, Jan 2nd, 2016, from our dealer in Holland that a stainless steel mini base ring presented with a problem on a Vortex container on its fourth jump (DOM October 2014), we are immediately advising all customers with a Vortex that has "DSF" stamped base rings (flip the base ring over and if its stamped DSF) to ground their equipment until we can ascertain which batch is impacted and obtain more detail from the manufacturer.

We are diligently pursuing this information in as quick a time as possible. We will post serial numbers of potentially affected Vortex's as soon as we have the manufacturers' confirmed information and steps that need to be taken to resolve this issue.

Please be assured that Parachute Systems will make all efforts as quickly as possible to resolve this issue.