



Deutscher Fallschirmsportverband (DFV) e.V.
Deutscher Aero-Club (DAeC) e.V. Luftsportgerätebüro
Verband unabhängiger Prüfer von Luftsportgerät e.V.

An alle Vereine/Schulen/ Fallschirmtechniker Fallschirmwarte

SICHERHEITSMITTEILUNG für Gurtzeuge

herausgegeben: 2018-07-19

Nummer: 02/2018

Bezug: Advisory Service Bulletin (PSB #2018-01) 2018-01

Betroffene Muster: Sport Vortex Containers

Grund: Eine geringe Anzahl an PODS mit koll. Hand de Ploy wurden im ersten Quartal 2018 mit Softlinks ausgestattet.

Status: **verpflichtend, vor dem nächsten Sprung**

Maßnahmen: Die Softlinks müssen gegen 5er Rapid Links (French Links) getauscht werden



Durchzuführen bis: **vor dem nächsten Sprung**

Bemerkungen: siehe originale Mitteilung im Anhang

Verteiler: Techniker, Warte, Händler, Vereine, Sprungzentren.

Dresden, den 2018-07-20

Referat Technik DFV

Ralf Homuth - Geschäftsstellenleiter VuPL



32 Melbourne Road, Dalbridge
Durban, SA 4014
Tel: (031) 304 8038 / Fax: (031) 304 8082
E-mail: support@parachutesystems.com
Web: www.parachutesystems.com


Reg No: 2002/050029/23

PRODUCT SERVICE BULLETIN 2018-01 (PSB # 2018-01)

TO BE IMPLEMENTED BEFORE NEXT JUMP

ISSUE DATE: 19th July 2018

A small quantity of new D-Bags (Main Parachute Deployment Bags) were produced by Parachute Systems (Pty)Ltd in the second quarter of 2018 with removable bridals. Our standard D-Bags have the bridal sewn directly onto the bag. **If you have one of these D-Bags, with a removable bridal, as pictured below, with a soft link retaining the bridal to the D-Bag, please strictly follow the instructions of this bulletin before next use.**



BACKGROUND:

A single case has been brought to our attention where the soft link pulled through the grommet during deployment of the main parachute leading to a pilot chute in tow.

SUBJECT: D-Bag with removable bridal on Vortex Harness Containers produced second quarter 2018.

STATUS: **Soft link needs to be replaced by a number 5 Rapid Link (French Link) before next use.**



32 Melbourne Road, Dalbridge
Durban, SA 4014
Tel: (031) 304 8038 / Fax: (031) 304 8082
E-mail: support@parachutesystems.com
Web: www.parachutesystems.com

Reg No: 2002/050029/23

IDENTIFICATION:

If your bridle is retained by a soft link it needs to be replaced by a number 5 Rapid Link (French Link) as illustrated in the below images.





32 Melbourne Road, Dalbridge
Durban, SA 4014
Tel: (031) 304 8038 / Fax: (031) 304 8082
E-mail: support@parachutesystems.com
Web: www.parachutesystems.com

Reg No: 2002/050029/23

DISTRIBUTION:

1. All registered owners affected by the Service Bulletin.
2. All Parachute Systems Dealers.
3. PIA
4. Company Social Media Pages

We apologize to all our customers who are affected by this. If you have any questions do not hesitate to contact us at support@parachutesystems.com. Please be assured that customer safety is our most important concern and we assure you of our best attention at all times.

Authorizing Authority

Chris Dales, Managing Director

32 Melbourne Road, Dalbridge
Durban, SA 4014
Tel: (031) 304 8038 / Fax: (031) 304 8082
E-mail: support@parachutesystems.com
Web: www.parachutesystems.com

A handwritten signature in black ink, appearing to read 'Chris Dales', is written over a horizontal dotted line.

Christopher Dales

Managing Director: Parachute Systems