

UNINSURED **UNITED PARACHUTE TECHNOLOGIES, LLC.**

---



---

March 17, 2014

To whom it may concern:

Uninsured United Parachute Technologies does not foresee any problems with the one-year repack cycle on all UPT products including the Vector III, Vector SE and Sigma Tandem Vector systems

The 3-ring system should still be inspected and lubricated on a regular basis while in use, and most importantly after long period of non-use.

The rest of the harness and container system should be visually inspected on a regular basis by the user for wear and tear on the system and external components, and appropriate action must taken if any problems or wear are found.

The systems should also be stored in a climate-controlled environment when not in use for extended periods.

Mark Procos

A handwritten signature in black ink, consisting of several sweeping, overlapping strokes.

General Manager