

SERVICE BULLETIN

DATE: Jan 15, 2009 **SERVICE BULLETIN #** SB-1545 **# OF PAGES: 1**

SUBJECT: Approval of Vigil 2 AAD into Rigging Innovations harness and container systems

STATUS: ADVISORY

IDENTIFICATION:

- 1. Vigil 2 AAD only. The Vigil 1 is **NOT** approved.
- 2. The following RI harness and container systems:
- Talon 1, Talon 2, Talon 3.0 including FS and FX.
- Telesis 1, Telesis 2, Telesis 3.0
- Flexon, Genera, and Voodoo

BACKGROUND: N/A

SERVICE BULLETIN:

RI harness and container systems listed above may be assembled with the Vigil 2, by a certificated and appropriately rated FAA master or senior parachute rigger or foreign equivalent. The assembly must be done in accordance with RI procedures. These procedures may be found on the RI website (www.rigginginnovations.com), and in the appropriate product owners manuals as revised after this date.

EFFECTIVE DATE: JANUARY 15, 2009

AUTHORITY:

SANDY R. REID, PRESIDENT

Rigging Innovations Inc. P O Box 86, Eloy AZ 85231 Telephone: 520.466.2655 FAX: 520.466.2656 E-mail sandy@rigginginnovations.com

DISTRIBUTION:

- 1. All registered owners affected by the Service Bulletin.
- 2. All Rigging Innovations Dealers.
- 3. All Parachuting Publications.
- 4. National Aero Clubs, Parachuting Section.
- 5. Military Parachute Organizations.
- 6. Parachute Industry Association.